



November 26, 2012

L-2012-402
10 CFR 50.73

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555


Re: St. Lucie Unit 1
Docket No. 50-335
Reportable Event: 2012-005-01
Date of Event: June 2, 2012

Unit 1 Reactor Trip on Turbine Trip

The attached supplement to Licensee Event Report 2012-005 is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Additionally, this Licensee Event Report was originally submitted per letter, L-2012-291, with an incorrect sequence number of 2012-007. The correct sequence number is 2012-005. This administrative error has been corrected and was discussed with NRR Project Manager, Tracy J. Orf, St. Lucie Plant Licensing Branch II-2.

Very truly yours,



Joseph Jensen
Site Vice President
St. Lucie Plant

JJ/rcs
Attachment

IE22
NRR

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resourse@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME

St. Lucie Unit 1

2. DOCKET NUMBER

05000335

3. PAGE

1 OF 3

4. TITLE

Unit 1 Reactor Trip on Turbine Trip

5. EVENT DATE

MONTH	DAY	YEAR
6	02	2012

6. LER NUMBER

YEAR	SEQUENTIA L NUMBER	REV NO.
2012	- 005	- 01

7. REPORT DATE

MONTH	DAY	YEAR
11	26	12

8. OTHER FACILITIES INVOLVED

FACILITY NAME	DOCKET NUMBER
NA	

9. OPERATING MODE

1

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)

- ☐ 20.2201(b)
☐ 20.2201(d)
☐ 20.2203(a)(1)
☐ 20.2203(a)(2)(i)
☐ 20.2203(a)(2)(ii)
☐ 20.2203(a)(2)(iii)
☐ 20.2203(a)(2)(iv)
☐ 20.2203(a)(2)(v)
☐ 20.2203(a)(2)(vi)

- ☐ 20.2203(a)(3)(i)
☐ 20.2203(a)(3)(ii)
☐ 20.2203(a)(4)
☐ 50.36(c)(1)(i)(A)
☐ 50.36(c)(1)(ii)(A)
☐ 50.36(c)(2)
☐ 50.46(a)(3)(ii)
☐ 50.73(a)(2)(i)(A)
☐ 50.73(a)(2)(i)(B)

- ☐ 50.73(a)(2)(i)(C)
☐ 50.73(a)(2)(ii)(A)
☐ 50.73(a)(2)(ii)(B)
☐ 50.73(a)(2)(iii)
☒ 50.73(a)(2)(iv)(A)
☐ 50.73(a)(2)(v)(A)
☐ 50.73(a)(2)(v)(B)
☐ 50.73(a)(2)(v)(C)
☐ 50.73(a)(2)(v)(D)

- ☐ 50.73(a)(2)(vii)
☐ 50.73(a)(2)(viii)(A)
☐ 50.73(a)(2)(viii)(B)
☐ 50.73(a)(2)(ix)(A)
☐ 50.73(a)(2)(x)
☐ 73.71(a)(4)
☐ 73.71(a)(5)
☐ OTHER

Specify in Abstract below
or in NRC Form 366A

10. POWER LEVEL

100%

12. LICENSEE CONTACT FOR THIS LER

NAME

Richard Sciscente - Principal Engineer, Licensing

TELEPHONE NUMBER (Include Area

Code) 772-467-7156

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU- FACTURE	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU- FACTURE	REPORTABLE TO EPIX
B	IT	CON	E232	YES	B	IT	DCC	E232	YES

14. SUPPLEMENTAL REPORT EXPECTED

☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE)☒ NO15. EXPECTED
SUBMISSION
DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 2, 2012 at 1935 with St. Lucie Unit 1 in Mode 1 at 100% power the reactor automatically tripped from normal full power operation due to a loss of load following a failure of the turbine control system (TCS). The reactor trip was uncomplicated and all control rod assemblies (CEAs) fully inserted. No automatic safety system actuations were required and none occurred. The reactor coolant system (RCS) heat removal was maintained with main feedwater (MFW) and steam bypass to the condenser. The Offsite power grid was available and stable.

The reactor trip on turbine trip was caused by loss of communications of the Drop 3 and Drop 53 controllers in the recently installed Ovation turbine control system (TCS). The direct cause for the failure of the primary controller (Drop 53) was an intermittent fault in the Remote Node Controller (RNC) or the Media Attachment Unit (MAU). The back up controller (Drop 3) failed due to a failed fiber optic (FO) cable field connector. The root cause of this event was ineffective design control for the TCS upgrade.

Immediate corrective actions taken included removing all questionable control modules and controllers. Corrective actions to prevent reoccurrence included providing additional guidance to operators in the annunciator response procedure and implementing a new normal operating procedure for the TCS.

This event had no effect on the health and safety of the public.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 2 of 3
		2012	- 005	- 01	

NARRATIVE**Description of the Event**

On June 2, 2012 at 1935 St. Lucie Unit 1 reactor automatically tripped from normal full power operation due to a loss of load following a failure of the turbine control system (TCS) [CON:IT]. No automatic safety system actuations were required and none occurred. The reactor coolant system (RCS) heat removal was maintained with main feedwater (MFW) and steam bypass to the condenser.

Cause

The reactor trip on turbine trip was caused by loss of communications of the Drop 3 and Drop 53 controllers in the Ovation turbine control system (TCS). The direct cause for the failure of the primary controller (Drop 53) was an intermittent fault in the Remote Node Controller (RNC) or the Media Attachment Unit (MAU) [DCC:IT]. The back up controller (Drop 3) failed due to a failed fiber optic (FO) cable field connector [CON:IT]. The root cause of this event was ineffective design control for the TCS upgrade.

Analysis of the Event

The primary function of the recently installed TCS is to control the proper speed and load of the turbine. The TCS consists of five controller cabinets each containing redundant controllers identified as "Drops." Failed Drops 3 and 53 are redundant Drops in one of the five controller cabinets. Prior to the event, Unit 1 was in Mode 1 and stable at 100% reactor power with no evolutions in progress or abnormal plant indications. At 1453, Drop 53 failed and transferred to Drop 3. At 1935, Drop 3 failed with no back-up causing the turbine / reactor trip.

Contributing factors to the ineffective design control for the TCS upgrade included weakness in the troubleshooting procedure, alarm response procedure, training on the new plant modification, workmanship and post maintenance testing. As a result, the unit was started up with TCS hardware deficiencies and a limited capability for responding to system malfunctions.

This licensee event report is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as "an event or condition that resulted in manual or automatic actuation of the reactor protection system including reactor scram or reactor trip."

Safety Significance

A risk assessment associated with Unit 1 automatic reactor trip event due to failure of TCS was developed. The conditional core damage probability (CCDP) and conditional large early release probability (CLERP) values were evaluated for the stated event and were found to be significantly below the thresholds required by RG-1.174 for the risk to be "Small", where CCDP is below 1.0E-06 and CLERP is below 1.0E-07. Therefore, it is concluded that this event had no effect on the health and safety of the public.

Prompt Corrective Action

All questionable control modules and the controllers were replaced.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 3 of 3
		2012	- 005	- 01	

NARRATIVE

Corrective Actions

The corrective actions below have been entered into the site corrective action program. Any changes to the actions will be managed under the corrective action program.

1. Additional guidance has been added to the annunciator response procedure for responding to TCS alarms.
2. A new normal operating procedure was developed and implemented for the TCS.
3. Additional TCS training is being provided to Operations, Engineering, and Maintenance.
4. New maintenance procedures were developed and implemented for the TCS.
5. The design control process is being revised to require risk based reviews for post maintenance test sequencing following risk significant plant modifications.

Similar Events

A search of the corrective action database for three years was performed and identified no issues that were related to the faults identified with this event.

Failed Component(s)

The primary controller (Drop 53) failed due to a fault in the Remote Node Controller or the Media Attachment Unit. The back up controller (Drop 3) failed due to a failed fiber optic cable field connector.

Manufacture: Model:

Emerson Electric Company

- 1C31203G01, Ovation RNC Electronics Module
- 1C31204G01, Ovation RNC Personality Module
- 1C31179G02, Ovation MAU Electronics Module
- 1C31181G02, Ovation MAU Personality Module